


High Speed T-Shirt Bag



名稱/內容 不一樣

Heat Cutting T-shirt Bag
Machine with 2
& 2 Servo Motors
Model: CW-800P-SV/CW-1000P-

High Speed Fully Automatic T-shirt
Machine With 2 Photocells &

Fully Automatic 6 lines



名稱/內容 不一樣

Double Layer (6 Lines) T-Shirt
Bag Cutting & Sealing Machine
Model: CWA2+6+P-800-
SV/CWA2+6+P-1000-SV

Fully Automatic High Speed Double
Layers 6 Lines T-Shirt Bag Making

Super High Speed T-Shirt Bag



名稱/內容 不一樣

Heat Cutting 2 or 4 Lines T-shirt
Bag Making Machine with 2
Photo Cells & 2 Servo Motors
Model: CW-1100P4-SV / CW-
1200P4-SV

Super High Speed Fully Automatic 2 or 4
Lines T-shirt Bag Making Machine With 2

Super High Speed T-Shirt Bag



名稱/內容 不一樣

2 Lines Heat Cutting T-Shirt
Making Machine With A
Packing Device Model:
800ATP-SV/ CW-1000A

Fully Automatic Super High Sp
T-shirt Bag Making Machine W
Packing Device By Servo Moto







578	573	572	548 SAND A	549 LVHU A	515 HIGHSUN DESHENG GPM / Ivy Machinery Ltd 9*15=135sqm	461 Tiantan	462 CHA A	389 JIAMI NG	388 Vaino Interna tional	361 COS MOS	304 Park JUE Pro Wen	337 HERO	338 Wensui	272 Samji n	275 Mo 273 TAI	248 SHAN DON	249 SHAN TOU	223 SACM I	222 QING ZHOU	191 BST	194 Polycel T	167 HSIEH HSU	158 TG	121 Kormc
577	571	570	546 MAST ER	547 RONG XIN		459 Kunshan	460 Taiz hou	387 ZF Active	386 CHAN GZHO	359 TUOH F	360 ACMT ECH	333 QLi	336 CONS TANT	246 HG	247 Tengmi n	220 TRUN GHAI	221 Zhejiang					161 Packon e	153 Lian You	120 HP Chemic als
576	569	568	544 JINJIU	545 JERRY SHAO		458 Ningbo Beilun Allway	381 NINGBO HAITAI	385 Shangh ai	355 Jurry Machin ery	356 JINGY F	334 COLE	332 Sincore	270 Techno Plast 54 sqm		245 Tederic 54sqm		214 FCS		185 YESWIN		160 POLYS TAR	36sqm	119 Minoc ha	
575 less on	567	566	540 XUSH ENG	543 DEMA II				541 Hongda																
	565	564																						

CALL 1



563 Worldly 15m x 9m= 135sqm				510 Kung Hsing	511 VICTOR	475 JWELL	476 S- DAI	438 NINGBO ALFA MACHINERY		368 CHESO / Haitian 6*18= 108 sqm	349 Jagmoh an	350 Ester Industr ies	323 Liansu machine ry	326 LIYAN G	282 Deguan x	283 POLY TECH	233 Starlinger & Co Gesellschaft 36 sqm		210 BOLE		180 Long New		155 VENUS PLASTI C	156 CHYI YANG	114 LUWA TEX 113 TA HAW						
Taiwan Pavilion				506 U-Tech	507 NEW STAR	471 PACIF IC		440 Baisha	441 Perfect halls		345 Basil	348 Parry	321 LONS SH	322 LONG LONG	280 XINZ HONG	281 UNEO N	235 Enercon	206 Shini	207 H. SAGA	151 MINLA ND	152 EVERGR EAT	112 JON WAI									
				504 HCI	505 King- Mo	469 KonRu n	470 TIAN YAN	442 HUAY IDE	443 GINZ A		346 OPPI	319 Illig	316 RR Plast	287 NINGBO CHUANGJI	231 FOMTEC	200 BORCH	175 Hyplas	176 Ming Wei	149 WEI JIN	150 TEX YEAR	111 Join Special										
					503 DESEL	467	468 SHA NTO	445 SHEN ZHEN	446 GBPI		341 RAJO O	342 WIND MOLL ER & HOLS		317 MAN- N	315 Palvi		252 HANK P	253 WEIER	226	171 Anchor Machin ery	172 Shine Kon	147 TRU- BRITE	146 HORNTACH	109 Margo							
527 UIC	529 Bright	531 GOOD PLUS	533 LEIBO	501 Fosita		465 CHIN A	466 FULIY TIAN	447 YOU FINE	448 GREE NSOU																						
526 DUN STIN	528 ZEAL AN	530 TIANJ IN	532 Lilian																												

400	401 SHEN	402 NING	403 ANXI	404 SANYI	405 Print	406 GAOT	408 Baiguo Pavilion	409 Nanyu	410 JUMB	412 MEGA 21sqm	300 Arti	301 CREA	302 Swasti	303 Ange	304 Merit	305 JIEFY	307 Techno	308 Swasti	309 Golden	310 HENG	311 Sanhua	312 Royai	100 TONG	101 Intang	104 Onetape	103 HaoSe	102 SPRING	105 Matila	107 Miami	108 Rajiv
-----	-------------	-------------	-------------	--------------	--------------	-------------	------------------------	--------------	-------------	-------------------	-------------	-------------	---------------	-------------	--------------	--------------	---------------	---------------	---------------	-------------	---------------	--------------	-------------	---------------	----------------	--------------	---------------	---------------	--------------	--------------

Registration
Counter



6 Factors to Consider When Choosing Melt Filters for Plastic Recycling Extrusion Machines



1. Your materials to be extrusion recycled
2. Your required production output
3. Your required contamination level for final product
4. Your extrusion screw diameter
5. Your manpower
6. The future maintenance costs